



10/068308

cofc

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No. : 6,762,462 B2
Issue Date : July 13, 2004
Inventor : Didier Belot

Certificate
SEP 01 2004
of Correction

Docket No. : 859063.511
Date : August 26, 2004

Mail Stop Certificate of Correction
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents:

A certificate of correction is respectfully requested in the above-identified patent.
The following errors have been made:

In Claim 5, line 6, as amended on December 31, 2003, --connect to a circuit-- was incorrectly changed to "connected to a circuit" in Claim 5, column 4, line 10 of the issued patent.


In Claim 9, line 3, as amended on December 31, 2003, --heavily doped segments-- was incorrectly changed to "heavily dosed segments" in Claim 9, column 4, line 33 of the issued patent.

Attached is form PTO/SB/44, which indicates the corrections to be made, by reference to the column and line numbers in the printed patent. Because the errors were made by the Patent Office, no fee is necessary. However if they are determined to be our errors, the

SEP 02 2004

Commissioner is hereby authorized to charge payment of any fees associated with this communication to Deposit Account No. 19-1090.

Respectfully submitted,
SEED Intellectual Property Law Group PLLC

A handwritten signature in black ink, appearing to read "Harold H. Bennett II", is written over a horizontal line.

Harold H. Bennett II
Registration No. 52,404

Enclosures:

Form PTO/SB/44

Postcard

SEED Intellectual Property Law Group PLLC
701 Fifth Avenue, Suite 6300
Seattle, Washington 98104-7092
Phone: (206) 622-4900
Fax: (206) 682-6031

510437

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 6,762,462 B2
DATED : July 13, 2004
INVENTOR : Didier Belot

It is certified that errors appear in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 4.

Line 10, "connected to a circuit" should read as --connect to a circuit--.

Line 33, "heavily dosed segments" should read as --heavily doped segments--.

MAILING ADDRESS OF SENDER:

Harold H. Bennett II
Seed Intellectual Property Law Group PLLC
701 Fifth Avenue, Suite 6300
Seattle, Washington 98104

PATENT NO. 6,762,462 B2

No. of additional copies

Page 1 of 1

Burden hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

SEP 02 2004